

**From:** [LGOIMA](#)  
**To:** Section 7(2)(a) - Protection of Privacy  
**Subject:** RE: LGOIMA request - Rubbish tips in Golden Bay - Reference: 2585 Friday, 10 January 2025 11:27:46 am  
**Date:** 2025 11:27:46 am  
**Attachments:** [LGOIMA 2585 Mohua Golden Bay landfills completed.pdf](#)  
[SiteSummary 252.pdf](#)  
[SiteSummary 160.pdf](#)  
[SiteSummary 170.pdf](#)  
[SiteSummary 184.pdf](#)  
[SiteSummary 1949.pdf](#)  
[SiteSummary 2113.pdf](#)  
[SiteSummary 255.pdf](#)  
[SiteSummary 835.pdf](#)

---

Kia ora Section 7(2)(a),

We refer to your official information request dated 20 December 2024. Our response is below:

**I am wanting to ascertain where there may have been open rubbish tips in Golden Bay and the dates they operated.** Section 7(2)(a) - Protection of Privacy told me there used to be one in Collingwood and I personally recall one being at Rototai adjacent to the Motupipi Estuary. You may know of others. This is in reference to a document I am writing on Southern Black-backed gulls in Mohua and their past access to open rubbish tips. I saw you on the 6pm news tonight and that is what prompted me to email you.

Please find **attached** information on the landfills in Mahua Golden Bay. This includes site summaries for each site and a table of sites and operational dates, if known. We note, the attached list does not include recycling stations, transfer stations of wastewater treatment sites:

- *LGOIMA 2585 Mohua Golden Bay landfills completed.pdf*
- *SiteSummary 252.pdf*
- *SiteSummary 160.pdf*
- *SiteSummary 170.pdf*
- *SiteSummary 184.pdf*
- *SiteSummary 1949.pdf*
- *SiteSummary 2113.pdf*
- *SiteSummary 255.pdf*
- *SiteSummary 835.pdf*

If you are unsatisfied with the Council's response, you have the right to seek an investigation and review by the Ombudsman. Information about how to make a complaint is available at [www.ombudsman.parliament.nz](http://www.ombudsman.parliament.nz) or freephone 0800 802 602.

Yours sincerely,  
Legal Services Officer

---

SCRID	SiteID	SiteName	Eastings	Northing	SiteType	Start Date	End Date
160	160	Collingwood RTS	1571540	5496271	Waste	1979	2000
170	170	Upper Takaka beside Cobb Road	1583958	5457683	Waste	1940	1996
184	184	Rototai	1586177	5479024	Waste	1950s	1994
252	252	Ernies Tip	1582468	5456390	Waste	1930	1995
255	255	Puponga DOC	1575497	5514492	Waste	Not known	Not known
835	835	Mangarakau closed landfill	1558430	5502400	Waste	May-99	Jun-99
1949	1949	Former Quarry Wharariki Road Reserve	1577238	5514186	Waste	Not known	Not known
2113	2113	Solly's	1570266	5493688	Waste	1998	current

Please note: this list does not include recycling centres, transfer stations or wastewater treatment

# Tasman District Council

## HAIL Register

<p><b>SiteID 252</b></p> <p><b>Valuation Assessment</b></p> <p><i>Property Affected</i> Ernies tip between road and river (beside Cobb Rd)</p> <p><i>Location</i> Easting = 1582468    Northing = 5456390</p> <p>Cobb Dam Road</p> <p><i>Also Known As</i> L49 Ernies Tip</p>
<p><b>Site Type Waste</b></p> <p><i>MfE Land Use</i> Contaminated Site</p> <p><i>National Environment</i> PSI Standard</p> <p><i>HAIL Primary Classification</i> Landfill sites.(G3)</p> <p><i>HAIL Secondary Classification</i></p> <p><i>Register Classification</i> Category 1(b) Managed for current land use</p> <p>A site which has been assessed as containing hazardous substances above background concentrations, BUT the risks to human health or the environment are considered to be acceptable through management or remediation interventions for restricted land use.</p>
<p><i>Land Use: Start Date</i></p> <p><i>End Date</i></p> <p><i>Storage Tanks - above ground</i></p> <p><i>Storage Tanks - underground</i></p> <p><i>File Number</i></p>
<p><i>LIM Statement</i> This site has been identified as being subject to the Resource Management (National Environmental Standard for Assessing and Managing Contaminants in Soil to Protect Human Health) Regulations 2011. This closed landfill has been capped, but still has the potential to discharge leachate or refuse if the cap is disturbed. Any future change of use, substantial earthworks or subdivision might require a site investigation report pursuant to the regulations. Please note this report may result in the need for resource consent under these regulations</p>
<p><i>Confirmed</i> N</p>

### Disclaimer

The Information provided is based on what is known to the Council and what is shown in Council records. Every care is taken collating this information, however the records may be incomplete, and therefore the information may be inaccurate.

# Tasman District Council HAIL Register

<p style="text-align: center;"><b>SiteID 160</b></p> <p><b>Valuation Assessment 1862005900</b></p> <p><i>Property Affected</i> Sec 393 TN OF Collingwood</p> <p><i>Location</i> Easting = 1571540    Northing = 5496271</p> <p style="text-align: center;">93 Collingwood-Bainham Main Road, Collingwood-Bainham</p> <p><i>Also Known As</i> Collingwood RTS</p>
<p style="text-align: center;"><b>Site Type Waste</b></p> <p><i>MfE Land Use</i> Contaminated Site</p> <p><i>National Environment</i> PSI <i>Standard</i></p> <p><i>HAIL Primary Classification</i> Landfill sites.(G3)</p> <p><i>HAIL Secondary Classification</i> Waste recycling or waste or wastewater treatment. (G6)</p> <p><i>Register Classification</i> Category 1(b) Managed for current land use</p> <p style="text-align: center;">A site which has been assessed as containing hazardous substances above background concentrations, BUT the risks to human health or the environment are considered to be acceptable through management or remediation interventions for restricted land use.</p>
<p><i>Land Use: Start Date</i> 1979</p> <p><i>End Date</i> 2000</p> <p><i>Storage Tanks - above ground</i></p> <p><i>Storage Tanks - underground</i></p> <p><i>File Number</i> RM090695 0960694</p>
<p><i>LIM Statement</i> This site is subject to the Resource Management (National Environmental Standard for Assessing and Managing Contaminants in Soil to Protect Human Health) Regulations 2011. This closed landfill received rubbish from the nearby district. There is the potential for leachate, landfill gas, visible rubbish and buried chemicals. The site also includes a current refuse transfer station and wastewater treatment facility. Any future change of use, substantial earthworks or subdivision might require a site investigation report pursuant to the regulations. Please note this report may result in the need for resource consent under these regulations.</p>
<p><i>Confirmed</i> N</p>

## Disclaimer

The Information provided is based on what is known to the Council and what is shown in Council records. Every care is taken collating this information, however the records may be incomplete, and therefore the information may be inaccurate.

# Tasman District Council HAIL Register

<p style="text-align: center;"><b>SiteID 170</b></p> <p><b>Valuation Assessment 1870035900</b></p> <p><i>Property Affected</i> Pt Sec 34 SQ 8</p> <p style="text-align: center;"><i>Location</i> Easting = 1583958    Northing = 5457683</p> <p style="text-align: center;">Cobb Valley Road (Harwood Farm)</p> <p style="text-align: center;"><i>Also Known As</i> L26 Upper Takaka beside Cobb Road</p>
<p style="text-align: center;"><b>Site Type Waste</b></p> <p style="text-align: center;"><i>MfE Land Use</i> Contaminated Site</p> <p style="text-align: center;"><i>National Environment</i> PSI Standard</p> <p style="text-align: center;"><i>HAIL Primary Classification</i> Landfill sites.(G3)</p> <p><i>HAIL Secondary Classification</i></p> <p style="text-align: center;"><i>Register Classification</i> Category 1(b) Managed for current land use</p> <p style="text-align: center;">A site which has been assessed as containing hazardous substances above background concentrations, BUT the risks to human health or the environment are considered to be acceptable through management or remediation interventions for restricted land use.</p>
<p style="text-align: center;"><i>Land Use: Start Date</i> 1940</p> <p style="text-align: center;"><i>End Date</i> 1996</p> <p><i>Storage Tanks - above ground</i></p> <p><i>Storage Tanks - underground</i></p> <p style="text-align: center;"><i>File Number</i></p>
<p><i>LIM Statement</i> This site has been identified as being subject to the Resource Management (National Environmental Standard for Assessing and Managing Contaminants in Soil to Protect Human Health) Regulations 2011. The bank of the stream has had a lot of local rubbish tipped down it and this has the potential to contaminate the adjacent stream and soil with leachate, visible rubbish and chemicals. Any future change of use, substantial earthworks or subdivision might require a site investigation report pursuant to the regulations. Please note this report may result in the need for resource consent under these regulations</p>
<p><i>Confirmed</i> Y</p>

## Disclaimer

The Information provided is based on what is known to the Council and what is shown in Council records. Every care is taken collating this information, however the records may be incomplete, and therefore the information may be inaccurate.

# Tasman District Council

## HAIL Register

<p style="text-align: center;"><b>SiteID 184</b></p> <p><b>Valuation Assessment 1871021400</b></p> <p><i>Property Affected</i> Lot 4 DP 2288</p> <p style="text-align: center;"><i>Location</i> Easting = 1586177    Northing = 5479024</p> <p style="text-align: center;">Rototai Road, Takaka adjacent to no. 184 Rototai Road</p> <p><i>Also Known As</i> L41 Rototai</p>
<p style="text-align: center;"><b>Site Type Waste</b></p> <p style="text-align: center;"><i>MfE Land Use</i> Contaminated Site</p> <p style="text-align: center;"><i>National Environment</i> PSI Standard</p> <p><i>HAIL Primary Classification</i> Landfill sites.(G3)</p> <p><i>HAIL Secondary Classification</i></p> <p><i>Register Classification</i> Category 1(b) Managed for current land use</p> <p style="text-align: center;">A site which has been assessed as containing hazardous substances above background concentrations, BUT the risks to human health or the environment are considered to be acceptable through management or remediation interventions for restricted land use.</p>
<p><i>Land Use: Start Date</i> 1950s</p> <p style="text-align: center;"><i>End Date</i> 1994</p> <p><i>Storage Tanks - above ground</i></p> <p><i>Storage Tanks - underground</i></p> <p style="text-align: center;"><i>File Number</i> RM090694</p>
<p><i>LIM Statement</i> This site is subject to the Resource Management (National Environmental Standard for Assessing and Managing Contaminants in Soil to Protect Human Health) Regulations 2011 (NESC). This property has been in use as a landfill for domestic refuse and some industrial commercial waste, which closed in 1994. From 2013, a cleanfill has been in operation on part of the property. There are ongoing checks on integrity of the landfill cover layer and bunded sides and reports are on file. Any future change of use, substantial earthworks or subdivision might require a site investigation report pursuant to the regulations. Please note this report may result in the need for resource consent under these regulations.</p>
<p><i>Confirmed</i> N</p>

### Disclaimer

The Information provided is based on what is known to the Council and what is shown in Council records. Every care is taken collating this information, however the records may be incomplete, and therefore the information may be inaccurate.

# Tasman District Council

## HAIL Register

<p align="center"><b>SiteID 1949</b></p> <p><b>Valuation Assessment 1860000703</b></p> <p><i>Property Affected</i></p> <p align="center"><i>Location</i> Easting = 1577238    Northing = 5514186</p> <p align="center">Road Reserve opposite 45 Wharariki Road</p> <p><i>Also Known As</i>    Former Quarry Wharariki Road Reserve</p>
<p align="center"><b>Site Type Waste</b></p> <p><i>MfE Land Use</i> TBA</p> <p><i>National Environment Standard</i> Not Assessed</p> <p><i>HAIL Primary Classification</i> Waste disposal to land (excluding where biosolids have been used as soil conditioners). (G5)</p> <p><i>HAIL Secondary Classification</i></p> <p><i>Register Classification</i> Category U - Unverified Hazardous Activity or Industry</p> <p align="center">A site for which past or present use has been reported as one that appears on the Hazardous Activities and Industries List (HAIL), but the reported use has not been confirmed.</p>
<p><i>Land Use: Start Date</i></p> <p align="center"><i>End Date</i></p> <p><i>Storage Tanks - above ground</i></p> <p><i>Storage Tanks - underground</i></p> <p align="center"><i>File Number</i></p>
<p><i>LIM Statement</i> This property has had an area of waste disposal to land. Photographs of test pits show an area of refuse adjacent to coast found. There are no site investigation reports on file. Any future change of use, substantial earthworks or further subdivision might require a site investigation report pursuant to the Resource Management (National Environmental Standard for Assessing and Managing Contaminants in Soil to Protect Human Health) Regulations 2011.</p>
<p><i>Confirmed</i> N</p>

### Disclaimer

The Information provided is based on what is known to the Council and what is shown in Council records. Every care is taken collating this information, however the records may be incomplete, and therefore the information may be inaccurate.



# Tasman District Council

## HAIL Register

<p style="text-align: center;"><b>SiteID 2113</b></p> <p><b>Valuation Assessment 1862023100</b></p> <p><i>Property Affected</i> All DP 876 Blk XIV Pakawau SD Blk IV Aorere SD</p> <p><i>Location</i> Easting = 1570266    Northing = 5493688</p> <p style="text-align: center;">Collingwood-Bainham Main Road, Collingwood-Bainham</p> <p><i>Also Known As</i> Solly's</p>
<p style="text-align: center;"><b>Site Type Waste</b></p> <p><i>MfE Land Use</i> TBA</p> <p><i>National Environment Standard</i> Not Assessed</p> <p><i>HAIL Primary Classification</i> Waste disposal to land (excluding where biosolids have been used as soil conditioners). (G5)</p> <p><i>HAIL Secondary Classification</i></p> <p><i>Register Classification</i> Category V - Verified Hazardous Activity or Industry- not sampled</p> <p style="text-align: center;">A site with the potential for contamination due to confirmation of past or present activity on the Hazardous Activities and Industries List (HAIL).</p>
<p><i>Land Use: Start Date</i> 1998</p> <p style="text-align: center;"><i>End Date</i></p> <p><i>Storage Tanks - above ground</i></p> <p><i>Storage Tanks - underground</i></p> <p style="text-align: center;"><i>File Number</i> RM170979</p>
<p><i>LIM Statement</i> This site has been identified as being subject to the Resource Management (National Environmental Standard for Assessing and Managing Contaminants in Soil to Protect Human Health) Regulations 2011. A consent for disposal of ash to land is on file for this property. Any future change of use, substantial earthworks or subdivision might require a site investigation report pursuant to the regulations. Please note this report may result in the need for resource consent under these regulations.</p>
<p><i>Confirmed</i> N</p>

### Disclaimer

The Information provided is based on what is known to the Council and what is shown in Council records. Every care is taken collating this information, however the records may be incomplete, and therefore the information may be inaccurate.

# Tasman District Council

## HAIL Register

<p><b>SiteID 255</b></p> <p><b>Valuation Assessment 1862051051</b></p> <p><i>Property Affected</i> Sec 1 SO 15200</p> <p><i>Location</i> Easting = 1575497    Northing = 5514492</p> <p>Off Wharariki Road</p> <p><i>Also Known As</i> Puponga DOC</p>
<p style="text-align: center;"><b>Site Type Waste</b></p> <p><i>MfE Land Use</i> TBA</p> <p><i>National Environment Standard</i> Not Assessed</p> <p><i>HAIL Primary Classification</i> Landfill sites.(G3)</p> <p><i>HAIL Secondary Classification</i> Mining industries (excluding gravel extraction) including exposure of faces or release of groundwater containing hazardous contaminants, or the storage of hazardous wastes including waste dumps or dam tailings. (E7)</p> <p><i>Register Classification</i> Category 1(b) Managed for current land use</p> <p>A site which has been assessed as containing hazardous substances above background concentrations, BUT the risks to human health or the environment are considered to be acceptable through management or remediation interventions for restricted land use.</p>
<p><i>Land Use: Start Date</i> 1960s</p> <p><i>End Date</i> 1988</p> <p><i>Storage Tanks - above ground</i></p> <p><i>Storage Tanks - underground</i></p> <p><i>File Number</i></p>
<p><i>LIM Statement</i> This property has a closed landfill associated with the historic Puponga Mine Site. The rubbish comprised household debris and car bodies and is covered with coal slack and earth and has potential to contaminate the soil or adjacent stream with refuse or leachate if the cover or cap is breached. This site has been identified as being subject to the Resource Management (National Environmental Standard for Assessing and Managing Contaminants in Soil to Protect Human Health) Regulations 2011. Any future change of use, substantial earthworks or subdivision might require a site investigation report pursuant to the regulations. Please note this report may result in the need for resource consent under these regulations.</p>
<p><i>Confirmed</i> Y</p>

### Disclaimer

The Information provided is based on what is known to the Council and what is shown in Council records. Every care is taken collating this information, however the records may be incomplete, and therefore the information may be inaccurate.

# Tasman District Council

## HAIL Register

<p style="text-align: center;"><b>SiteID 835</b></p> <p><b>Valuation Assessment 1870036315</b></p> <p><i>Property Affected</i> Pt Sec 1 SQ 17 and Sec 2 SQ 17</p> <p><i>Location</i> Easting = 1558430    Northing = 5502400</p> <p style="padding-left: 40px;">20mx20x 4m pit 30m from estuary, 28m above SL</p> <p><i>Also Known As</i>    Mangarakau closed landfill</p>
<p style="text-align: center;"><b>Site Type Waste</b></p> <p><i>MfE Land Use</i> Land Use Information</p> <p><i>National Environment Standard</i> Not Assessed</p> <p><i>HAIL Primary Classification</i> Landfill sites.(G3)</p> <p><i>HAIL Secondary Classification</i></p> <p><i>Register Classification</i> Category 1(b) Managed for current land use</p> <p style="padding-left: 40px;">A site which has been assessed as containing hazardous substances above background concentrations, BUT the risks to human health or the environment are considered to be acceptable through management or remediation interventions for restricted land use.</p>
<p><i>Land Use: Start Date</i> May 1999</p> <p style="padding-left: 40px;"><i>End Date</i> June 1999</p> <p><i>Storage Tanks - above ground</i> nil</p> <p><i>Storage Tanks - underground</i> nil</p> <p style="padding-left: 40px;"><i>File Number</i> NN990159L</p>
<p><i>LIM Statement</i> This property has the Mangarakau closed landfill and is capped. This was a one off burial site created in 1999 from the municipal and farm rubbish retrieved from the edge of the adjacent estuary and is not receiving current refuse. This site has been identified as being subject to the Resource Management(National Environmental Standard for Assessing and Managing Contaminants in Soil to Protect Human Health) Regulations 2011.</p> <p style="padding-left: 40px;">Any future change of use, substantial earthworks or subdivision might require a site investigation report pursuant to the regulations. Please note this report may result in the need for resource consent under these regulations.</p>
<p><i>Confirmed</i> Y</p>

### Disclaimer

The Information provided is based on what is known to the Council and what is shown in Council records. Every care is taken collating this information, however the records may be incomplete, and therefore the information may be inaccurate.